






RDH Electrical / Rock Volt

TEREX Panel – Motor Start – KM1

Ore Sorter, Meeka - control & power schematic, 24VDC control / 415VAC 3~ power · SHEET 2: KM1



CHECKED: Terex Engineer

NAME: \_\_\_\_\_

SIGN: \_\_\_\_\_

DATE: \_\_\_\_\_

DRAWN: Nina Voss

DATE: 14/10/26

DWG: Terex\_Motor\_Start\_Rewire\_Sht2\_KM1

SHEET: 2 of 6

SIZE: A3

REV AE

FROM SHEET 2  
+24VDC (+)

FROM SHEET 2  
0VDC (-)

TO SHEET 4

TO SHEET 4

RDH Electrical

RDH Electrical / Rock Volt

Motor Start – KM2

Ore Sorter, Meeka - control & power schematic, 24VDC control / 415VAC 3~ power



CHECKED: Terex Engineer

NAME: \_\_\_\_\_

SIGN: \_\_\_\_\_

DATE: \_\_\_\_\_

DRAWN: Nina Voss

DATE: 14/10/26

DWG: Terex\_Motor\_Start\_KM2

SHEET: 3 of 6

SIZE: A3

REV C

FROM SHEET 3  
+24VDC (+)

FROM SHEET 3  
0VDC (-)

TO SHEET 5

TO SHEET 5

RDH Electrical

RDH Electrical / Rock Volt

Motor Start – KM3

Ore Sorter, Meeka - control & power schematic, 24VDC control / 415VAC 3~ power



CHECKED: Terex Engineer

NAME: \_\_\_\_\_

SIGN: \_\_\_\_\_

DATE: \_\_\_\_\_

DRAWN: Nina Voss

DATE: 14/10/26

DWG: Terex\_Motor\_Start\_KM3

SHEET: 4 of 6

SIZE: A3

REV C

FROM SHEET 4  
+24VDC (+)

FROM SHEET 4  
0VDC (-)

TO SHEET 6

TO SHEET 6

RDH Electrical

RDH Electrical / Rock Volt

Motor Start – KM4

Ore Sorter, Meeka - control & power schematic, 24VDC control / 415VAC 3~ power



CHECKED: Terex Engineer

NAME: \_\_\_\_\_

SIGN: \_\_\_\_\_

DATE: \_\_\_\_\_

DRAWN: Nina Voss

DATE: 14/10/26

DWG: Terex\_Motor\_Start\_KM4

SHEET: 5 of 6

SIZE: A3

REV C

FROM SHEET 5  
+24VDC (+)

FROM SHEET 5  
0VDC (-)

RDH Electrical

RDH Electrical / Rock Volt

Motor Start – KM5 & KM6 (parallel)

Ore Sorter, Meeka - control & power schematic, 24VDC control / 415VAC 3~ power



CHECKED: Terex Engineer

NAME: \_\_\_\_\_

SIGN: \_\_\_\_\_

DATE: \_\_\_\_\_

DRAWN: Nina Voss

DATE: 14/10/26

DWG: Terex\_Motor\_Start\_KM56

SHEET: 6 of 6

SIZE: A3

REV C